

## Replacement Loom for Older Shire Engines

### Replacement for RDG2058890 & RDG2057378

For loom replacement on older Shire engines You will need to fit the most recent loom RDG205A21, as the early engines did not have the relay and timer fitted these will need to be added. This prevents the stop solenoid from burning out from over cranking if fuel system has not been bled correctly.

#### New Loom RDG205A21



#### Glow Relay 119650-77911



#### Timer 129211-77920



**A connection will need to be made and then cable tied to the loom.**