

STANDARD AUTO-TENSIONER KIT

Standard spring tensioner needs changing after 750 hours

Part No. RDG702B30


Kit contents:

Part	Part No	Qty	Description
1	RDG502B1	1	Auto Belt tensioner
2	RDG401A306	1	Shire 50 Auto Tensioner Brkt. Port
3	RDG401A307	1	Shire Auto Tensioner Brace Brkt.
4	RDG401A429	1	Shire 50 Hyb Alternator Top Brkt.
5	RDG1417	2	M6 x 25 Cap Head Screw SS
6	RDG1622	2	M6 Flat Washer Form B SS
7	RDG1255	4	M8 x 30 Hex Head Screw SS
8	RDG5976	2	M8 x 100 CSK SKT Screw BZP
9	RDG986	1	M8 Flat Washer Form A BZP
10	RDG1029095	1	M10 x 30 Hex Head Screw SS
11	RDG10110173	1	M10 x 50 CSK Screw BZP
12	RDG102B5	1	M10 x 100 Cap Head Bolt BZP
13	RDG628	5	M10 Flat Washer Form A SS
14	RDG716	2	M10 "P" Type (Full) Nylock Nut BZP
15	RDG5731	1	Spacer 20OD x 10.5ID x 8mm Long
16	RDG103A196	1	M8 "T" Type Half Nylock Nut BZP
17	RDG549	4	M8 Spring Washer SS
18	RDG561	2	M6 Spring Washer SS
19	RDG1111	1	M10 Spring Washer SS
20	RDG105A7	1	M10 x 25 OD BZP Washer
21	RDG669	3	M10 Flat Washer Form A BZP
22	RDG1068008	4	Spacer 10.5IDx20ODx10mm
23	RDG102A90	4	M10 x 40 Hex Head Bolt BZP


1



2



3



4



5



6



7



8



9



10



11



12



13



14



15



16



17




18



19



20



21



22



23

